MONITORING GREEN INFRASTRUCTURE FUNCTION IN RHODE ISLAND






NARRAGANSETT BAY ESTUARY PROGRAM







TLC2000 2022/08/23 14:25:01





























PLUS EXISTING PRECIPITATION DATA

NOAA/NWS/CoCoRaHS










TLC200 PRO 2022/09/25 17:35:10



What did we find out?

CHALLENGES WITH:

DESIGN CONSTRUCTION MAINTENANCE COMBINATION OF ALL 3 Sizing - Capacity



Sizing - Capacity



debris blocking inlet



vegetation blocking inlet



Sizing – Capacity

deposited sediment has changed grade



Sizing – Capacity deposited sediment has changed grade



Sizing – Capacity deposited sediment has changed grade




decreased volume capacity




decreased volume capacity



deposited sediment has slowed infiltration rates



Roadway/Parking lot grade




Inlet slope not steep enough





Not constructed as designed















Take Home Message

Continue to monitor and inspect your green infrastructure after implementation.

